Scope of	Work for Property Lo	cated	at:		<u>3161</u>	North 24th Street	
	Property is: Single Fa	amily	4	Duplex		Other □	
Date:	1/3/2017						
take no respo		d after the	insp	ection dat	e, or for o	y of Milwaukee, the Redevelopment Authornissions through error or oversight. The Grant or HOME programs.	
Exterior (Condition Report						
Location Site	Required Work Landscaping	n/a _	7	Yes 🗌	Note/0	Comments olp	\$ Cost
	Steps/Handrails	n/a	√	Yes 🗌			\$
	Service walks	n/a		Yes 🗸	assum	ed - snow covered	\$ 1,400.00
	Fencing	n/a		Yes 🗹			\$ 500.00
	Parking	n/a	√	Yes 🗌			\$
	Retaining walls	n/a	4	Yes 🗌			\$
	Other	n/a		Yes 🗌			\$
	Other	n/a		Yes 🗌			\$
Garage	Singles: repair	n/a	√	Yes 🗌			\$
	Shingles: Roof over existing	n/a	7	Yes 🗌			\$
	Shingles:Tear off & re-roof	n/a		Yes 🗸	assum	ed snow covered	\$ 4,500.00
	Gutters/downspouts	n/a	7	Yes 🗌			\$
	Flashing	n/a	7	Yes 🗌			\$
	Eaves	n/a		Yes 🗸	fascia/	soffit	\$ 300.00
	Siding	n/a		Yes 🗸			\$ 2,500.00
	Doors	n/a		Yes 🗸	overhe	ead & service	\$ 1,600.00
	Windows	n/a	√	Yes 🗌			\$
	Slab	n/a	√	Yes 🗌			\$
	Paint	n/a	7	Yes 🗌			\$
	Other	n/a		Yes 🗸	structi	ural damage-hit by vehicle	\$ 3,000.00
	Other	n/a		Yes 🗸	permit		\$
Porches	Roof	n/a	√	Yes 🗌			\$
	Deck-upper	n/a	4	Yes 🗌			\$
	Decklower	n/a		Yes 🗸			\$ 2,800.00
	Steps/handrails	n/a	4	Yes			\$
	Ceiling	n/a	4	Yes 🗌			\$
	Guardrails	n/a	4	Yes 🗌			\$
	Structural	n/a	4	Yes			\$
	Paint	n/a		Yes 🗸			\$ 550.00
	Other	n/a		Yes 🗸	permit		\$ 85.00

House

Chimney	n/a 🗸 Yes 🗌	\$
Shingles: repair	n/a ✓ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes □	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 9,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,200.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a Yes 🗸	\$ 800.00
Siding	n/a ☐ Yes ☑	\$ 4,500.00
Storm Doors	n/a ✓ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 350.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 620.00
Paint	n/a Yes previously painted surfaces	\$ 1,600.00
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes □	\$
Other	n/a 🗌 Yes 🗹 window screens	\$ 125.00
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:* \$

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

35,430.00

Interior Co	ondition Report					
	Unit: Entire unit (single family) Upper unit of duplex	✓ □		Lower unit of duplex Other		
Mechanical Heating	Required Work					
	Repair/replace boiler	n/a ☑	Yes 🗌			\$
	Repair radiation	n/a 🔽	Yes 🗌			\$
	Repair/replace furnace	n/a 🔽	Yes 🗌			\$
	Repair ductwork	n/a 🗸	Yes 🗌			\$
	Replace thermostat	n/a 🔽	Yes 🗌	_		\$
	Repair/replace grilles	n/a 🔲	Yes ✓	_		\$ 60.00
Electrical	Tune boiler/furn. insp ht exchang	€n/a □	Yes 🗸			\$ 400.00
	Repair/replace receptacles	n/a 🗌	Yes 🗸			\$ 400.00
	Repair/replace switches	n/a 🔲	Yes 🗸	_		\$ 400.00
	Repair/replace fixtures	n/a 🔲	Yes ✓	_		\$ 400.00
	Install outlets and circuits	n/a 🔽	Yes 🗌	_		\$
	Install outlets and circuits	n/a 🔽	Yes 🗌			\$
	Install outlets and circuits	n/a ✓	Yes 🗌			\$
	Install outlets and circuits	n/a 🔽	Yes 🗌	_		\$
	Upgrade service	n/a 🔲	Yes 🗸	_		\$ 1,750.00
	Other	n/a 🗌	Yes 🗌			\$
	Other	n/a 🗌	Yes 🗌			\$
Plumbing	Repair/replace kitchen sink	n/a 🗸	Yes 🗌			\$
	Repair/replace kitchen sink fauce	e n/a	Yes 🗌	_		\$
	Repair/replace tub	n/a 🗸	Yes 🗌	_		\$
	Repair/replace tub faucet	n/a 🗸	Yes 🗌			\$
	Repair/replace toilet	n/a 🗸	Yes 🗌			\$
	Repair/replace lavatory	n/a ✓	Yes 🗌			\$
	Repair/replace lavatory faucet	n/a 🗸	Yes 🗌			\$
	Repair/replace wash tub	n/a 🗸	Yes 🗌			\$
	Repair/replace wash tub faucet	n/a ✓	Yes 🗌			\$
	Unclog piping:	n/a 🗸	Yes 🗌			\$
	Repair drain/waste/vent piping	n/a 🔲	Yes 🗸			\$ 250.00
	Repair water piping	n/a 🗸	Yes 🗌			\$
	Repair/replace water heater	n/a 🗸	Yes 🗌			\$
	Other	n/a 🔲	Yes 🗌			\$
	Other	n/a 🗌	Yes 🗌			\$

Windows								
	Replace broken glass	n/a 🔽] Y	es			\$	
	Repair or replace sash	n/a] Y	es		_	\$	
Doors			- V				•	202.00
	Repair or replace doors	n/a L	_ Y	es	1	_	\$	380.00
	Repair or repl. locks/latches	n/a _] Y	es	4	Self Help	\$	110.00
Walls/Ceilin	Repair or repl. @ defective	n/a [] Y	es	1		\$	900.00
Paint	Repair or repl. @ defective	n/a 🗆] Y	es	7		\$	700.00
Fire Safety							·	
r lie Salety	Install smoke/CO alarm:bsmt.	n/a _] Y	es	4	Self Help	\$	85.00
	Install smoke/CO alarm: 1st flr.	n/a _] Y	es	√	Self Help	\$	85.00
	Install smoke/CO alarm: 2nd flr.	n/a 🗌] Y	es	√	Self Help	\$	85.00
Handrails	Repair/replace defective	n/a _] Y	es	7	Self Help	\$	250.00
Stairs	Repair defective	n/a [1 Y	es	7		\$	1,300.00
Floors	•						·	•
Other	Repair defective	n/a _	_ Y	es	1		\$	2,400.00
Other		n/a [] Y	es	√	tub surround	\$	500.00
		n/a [] Y	es	V	guardrail @ 2nd floor steps	\$	300.00
		n/a 🗆] Y	es	V	some 1st floor joists burned - assume	\$	
		n/a _	Y	es		structurally sound, but repairs may be required	\$	1,200.00
						Interior: Estimated Cost:	\$	11,955.00
						Total Exterior and Interior Cost:*	\$	47,385.00

Inspected by: Tom Frank Date: 12/22/16

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.